

Job Sheet

Date/Time	CRC Number/PE Number/Name
14.9.2016 1300	
	Return to swing bridge area and commence search/examination
	Use anglers access to small camping ground, identify location photo was taken from, on true right of Hurunui River. No obvious sign of cattle in this area of recent time. What appeared to be an Island in said photo is a small peninsular.
	Go to swing bridge carpark. Walk across swing bridge to true left bank, there is obvious sign of cow dung in the area, no bank damage or pugging was seen. It is possible that some cows are waiting in this location to be brought back across the river.
	Follow the track around to the Jolly Brook, obvious sign where the cows had been, along the track, there was some pugging at the toe of the first terrace, also pig rooting this was 30 meters from the river and considered less than minor. Where the track sign for Gabriel's track is there is very little sign of cattle. I walked approximately 300m further up Jolly Brook and saw no sign of any cattle activity.
	Return back to vehicle via different route, no sign of cow effluent in river, Note: The Hurunui had had a small fresh through it between when photo allegedly taken and complaint received.
	Take photos (poor photos camera issue)

